


. . . . 2/4

Load x -> R1 Load y -> R2 FT_MULT (R1,R2) -> R3 Store R3



3/4



4/4

Routines not using F-T instructions 306

Routines using F-T instructions 304

Routines not using F-T instructions 306

Program B not using fault tolerance <u>303</u>

Program A using fault tolerance <u>302</u>